



This Service Information bulletin supersedes S.I. B24 05 06 **dated September 2006.**

NEW designates changes to this revision

SUBJECT

Delayed Upshift May Occur Uphill in 3rd or 4th Gear

MODEL

E83, X3 with M54 and GM5

SITUATION

The customer complains that the transmission will not upshift, usually after going up a slight incline, and stays in either 3rd or 4th gear too long.

CAUSE

Calibration sensitivity in the Hill recognition program of the EGS transmission module.

NEW CORRECTION

On a customer complaint basis only, perform the retrofit option "Hills program" using only

Progman V23.02.00 or higher.

NEW WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty.

Defect Code	Refer to KSD
Labor Operation:	Refer to KSD
Labor Allowance:	Refer to KSD

[Copyright © 2006 BMW of North America, LLC]