

<u>11 05 11</u>	SI	December 2011	Engine Removal and Installation Tips	All
<u>11 01 10</u>	SI	April 2010	BMW ALPINA B7 Engine Oil Filter	E65
<u>11 06 09</u>	SI	January 2011	Crankshaft Seal and Bed Plate Sealer	All
<u>11 01 09</u>	SI	March 2012	CPO Inspect. Guidelines-Engine Inspection on Veh w/Extended Oil Svc Intervals	E39, E46, E53, E60, E61, E63, E64, E65, E66, E70, E71, E82, E83, E85, E88, E90, E91, E92, E93
<u>11 04 08</u>	SI	May 2012	TeileClearing for Engine Components	E53, E60, E61, E63, E64, E65, E66, E70, E71, E82, E83, E85, E86, E88, E89, E90, E91, E92, E93, F01, F02, F07, F10, F25, F30
<u>11 03 08</u>	SI	August 2011	Crankcase Ventilation System Diagnosis and Measurement	All
<u>11 12 07</u>	SI	October 2007	N62 and N62TU Engine Replacement	E53, E60, E63, E64, E65, E66, E70
<u>11 06 07</u>	SI	May 2007	Service Action: Replace the Radial Compressor Centrifugal Clutch	E65
<u>11 04 07</u>	SI	August 2007	Testing Induction Systems Using the VACUTEK Smoke Machine	All
<u>11 01 07</u>	SI	March 2009	N62 and N62TU Crankcase Ventilation System - Cold Climate Conditions	E53, E60, E63, E64, E65, E66, E70
<u>11 09 06</u>	SI	October 2006	Replacement of Valvetronic Components - Helpful Hints	E65, E66
<u>11 07 06</u>	SI	October 2006	N62 Engine - Rough Idle at Operating Temperature	E60, E63, E64, E65, E66
<u>11 04 06</u>	SI	June 2006	Engine, Transmission, or Clutch Related Complaints	E24, E28, E30, E31, E32, E34, E36, E38, E39, E46, E52, E53, E60, E61, E63, E64, E65, E66, E83, E85, E90, E91
<u>11 03 06</u>	SI	June 2006	Recall 06E-A02: N62 - Crankcase Ventilation Valves Replacement	E53, E60, E63, E64, E65, E66
<u>11 09 05</u>	SI	April 2006	Non-Return Valve Parts Found in Engine Oil Filter During Engine Oil Service	E53, E60, E63, E64, E65, E66
<u>11 08 05</u>	SI	October 2005	Service Action: N62TU Coolant Supply Hose Replacement	E65, E66
<u>11 07 05</u>	SI	July 2005	N62 and N62TU Water Pump Replacement	E53, E60, E63, E64, E65, E66
<u>11 03 05</u>	SI	June 2005	N62 and N62TU Valve Cover and Valve Cover Gasket Replacement	E53, E60, E63, E64, E65, E66
<u>11 11 03</u>	SI	January 2005	Service Action: Non-Return Valve Replacement	E65, E66
<u>11 05 03</u>	SI	September 2003	Recall Campaign 03V-324: Retorque of Oil Drain Plug Located in Oil Filter Cover	E65, E66
<u>11 03 02</u>	SI	May 2002	Coolant Leak at Water Pump	E65, E66
<u>11 02 02</u>	SI	March 2002	Intake Boot at Throttle Body	E65, E66
<u>11 01 02</u>	SI	February 2002	Oil Level Sensor Leak	E65, E66
<u>11 08 98</u>	SI	June 2006	BMW Engine Oils	E38, E39, E46, E52, E53, E60, E61, E63, E64, E65, E66, E83, E85, E90, E91
<u>11 01 92</u>	SI	January 1992	Engine Hydraulic Lock	All
<u>11 11 90</u>	SI	March 2012	Engine Oil Capacities	E24, E28, E31, E32, E34, E36, E38, E46, E52, E53, E60, E61, E63, E64, E65, E66, E70, E71, E82, E83, E85, E86, E88, E89, E90, E91, E92, E93, F01, F02, F04, F07, F10, F12, F13, F25, F30

<u>11 05 84</u>	SI	March 1985	Engine Oil Consumption Complaint Verification	All
<u>12 02 12</u>	SI	February 2012	N54, N73: Various Drivability Complaints & Service Engine Soon Lamp Illuminated	E60, E61, E65, E66, E71, E82, E88, E89, E90, E92, E93, F01, F02
<u>12 15 10</u>	SI	October 2010	Voluntary Emissions Recall Campaign 10E-A01:Program Control Units (DME Retrofit)	E65, E66
<u>12 09 10</u>	SI	May 2010	E72 Hybrid CAN Errors	All
<u>12 02 10</u>	SI	March 2010	N51 or N52K Important Information when Programming the DME	All
<u>12 26 09</u>	SI	October 2009	N62TU: EDK Throttle Potentiometer Faults - Diagnosis	E60, E63, E64, E65, E66, E70
<u>12 24 08</u>	SI	September 2008	Service Action: E65 and E66 with N62TU or N73-OBd Communication	E65, E66
<u>12 23 08</u>	SI	July 2008	Service Action: E65 and E66 with N62, N62TU, or N73 - OBd Communication	E65, E66
<u>12 17 08</u>	SI	June 2008	Service Action: E65 and E66 with N62, N62TU, or N73 - OBd Incompliance	E65, E66
<u>12 15 08</u>	SI	August 2008	E65, E66 with N62TU - Various Driveability Complaints	E65, E66
<u>12 26 07</u>	SI	January 2008	BMW ALPINA B7: The Service Engine Soon Light is On	E65
<u>12 22 07</u>	SI	May 2012	TeileClearing (Enhanced Technical Support) for DME	E53, E60, E61, E63, E64, E65, E66, E70, E71, E82, E83, E85, E86, E88, E89, E90, E91, E92, E93, F01, F02, F07, F10, F12, F13, F25, F30
<u>12 14 07</u>	SI	January 2008	Voluntary Emissions Recall 07E-A04: BMW ALPINA B7-Reprogram Vehicle (DME)	E65
<u>12 05 07</u>	SI	April 2008	Diagnosis: Low Oil-Level Warning Message is Displayed	E60, E61, E63, E64, E65, E66, E70, E83, E85, E86, E90, E91, E92, E93
<u>12 50 06</u>	SI	November 2006	OBd II Fault Codes List in TIS	E60, E63, E64, E65, E66, E83, E85, E90, E91, E92
<u>12 43 06</u>	SI	October 2006	N62 DME ME9.2.1 Engine Difficult to Restart at Operating Temperatures	E60, E63, E64, E65, E66
<u>12 33 06</u>	SI	October 2006	Various Complaints Caused by Defective Oil Level Sensor-Diagnostic Hints	E46, E53, E60, E63, E64, E65, E66, E83, E85
<u>12 32 06</u>	SI	November 2006	Powertrain Drivability Complaints	E31, E36, E38, E39, E46, E52, E53, E60, E61, E63, E64, E65, E66, E70, E83, E85, E90, E91, E92
<u>12 28 06</u>	SI	October 2006	DME Fault Code 27CD	E53, E60, E65, E66
<u>12 27 06</u>	SI	November 2006	DME Fault Codes 278B and 278D	E53, E60, E65, E66
<u>12 15 06</u>	SI	October 2006	N73 - Erroneous Low Oil Level Warning Message While Driving	E65, E66
<u>12 12 06</u>	SI	April 2007	N62TU - Diagnosis for DME FC 2A90	E60, E63, E64, E65
<u>12 05 06</u>	SI	May 2006	N62TU - Diagnosis of Mixture Adaptation Faults	E65, E66
<u>12 27 05</u>	SI	April 2011	N62TU - Engine Pinging and Idle Fluctuation	E60, E63, E64, E65, E66
<u>12 20 05</u>	SI	October 2005	Loss of Power While Decelerating and Turning or Coming to a Stop	E60, E63, E64, E65, E66
<u>12 18 05</u>	SI	May 2008	N62 and N62TU Engine Diagnosis Test Plan Updates	E53, E60, E63, E64, E65, E66, E70
<u>12 15 05</u>	SI	April 2010	N62 - Diagnosis of DME ME9.2 Map Thermostat Fault 2EF4/279B	E60, E63, E64, E65, E66
<u>12 14 05</u>	SI	September 2005	N62TU CBS Engine Oil Service Indicates 19,000 Miles	E65, E66

<u>12 13 05</u>	SI	October 2005	Voluntary Emissions Recall Campaign 05E-A01: BREMI Ignition Coils Replacement	E39, E46, E53, E65, E66, E83, E85
<u>12 02 05</u>	SI	June 2005	Service Action: Replacement of Camshaft Sensors	E65, E66
<u>12 01 05</u>	SI	December 2010	High Performance Iridium Spark Plug/Spark Plug Application Chart	All
<u>12 09 04</u>	SI	September 2008	Special DME and EGS Programming - Shipping Procedure	All
<u>12 05 04</u>	SI	October 2005	Voluntary Emissions Recall 04E-A04: Reprogram DME for Oxygen Sensors Diagnostics	E53, E60, E63, E64, E65, E66
<u>12 04 04</u>	SI	July 2004	Safety Recall Campaign 04V-344: DME Replacement on N62/N73 Engines	E53, E60, E63, E64, E65, E66
<u>12 07 03</u>	SI	September 2003	Recall 03V-240: E65/66 with N62 DME Reprogramming	E65, E66
<u>12 06 03</u>	SI	June 2003	Setting OBD Readiness Code Prior to State Inspection	E36, E38, E39, E46, E52, E53, E60, E61, E63, E64, E65, E66, E70, E82, E83, E85, E86, E88, E90, E91, E92, E93
<u>12 06 02</u>	SI	August 2002	Service Action to Replace Integrated Supply Module (IVM)	E65, E66
<u>12 05 02</u>	SI	May 2002	Engine Oil Level Sensor Faults	E65
<u>12 04 02</u>	SI	March 2002	E65, New DME Feature	E65, E66
<u>12 03 89</u>	SI	March 1989	High Pressure Engine Steam Cleaning	All
<u>13 02 11</u>	SI	June 2011	High-pressure Direct Injection Fuel System Repairs	All
<u>13 05 10</u>	SI	April 2011	Testing Fuel Composition	All
<u>13 06 09</u>	SI	June 2009	Fuel Injection and Induction System Cleaning-Customer Information Brochure	E46, E53, E60, E61, E63, E64, E65, E66, E70, E83, E85, E86, E90, E91, E92, E93
<u>13 01 07</u>	SI	August 2010	Fuel Injection and Induction System Cleaning	All
<u>13 07 06</u>	SI	November 2006	Gasoline Quality & Detergent Additives - Customer Information Brochure	All
<u>13 05 06</u>	SI	August 2010	BMW Group Fuel System Cleaner Plus	All
<u>13 03 06</u>	SI	May 2006	Fuel Pump Failure after Refueling with Ethanol Fuel Blend	All
<u>13 02 06</u>	SI	September 2006	TOP TIER Detergent Gasoline in BMW Vehicles	All
<u>13 01 06</u>	SI	May 2011	Alcohol Fuel Blends in BMW Vehicles	All
<u>13 01 02</u>	SI	June 2002	Service Action - Throttle Housing Assembly	E65, E66
<u>16 04 12</u>	SI	February 2012	Fuel Tank Access Cover Locking Ring Torque Specification Missing from ISTA/D	E39, E46, E52, E53, E60, E61, E63, E64, E65, E66, E83, E85
<u>16 11 10</u>	SI	April 2011	Fuel Cap Tether Broken or Lost	All
<u>16 02 09</u>	SI	December 2009	Fuel Level Sensor Repairs	All
<u>16 01 07</u>	SI	September 2011	Testing Evaporative Systems for Leaks	All
<u>16 03 05</u>	SI	September 2005	Erratic Fuel Level Display	E65, E66
<u>16 01 02</u>	SI	June 2002	Insufficient Fuel Transfer Inside Fuel Tank; Diagnostic Hints	E65, E66
<u>16 04 00</u>	SI	December 2000	Check Engine Light Illuminated, Faults Stored in DME/ECM	All
<u>17 01 10</u>	SI	March 2010	Proper Evacuation and/or Filling of Cooling System after Repairs	All
<u>17 01 07</u>	SI	June 2010	Long-Term Antifreeze/Coolant: Maintenance, Repairs & Replacement Requirements	All
<u>17 04 06</u>	SI	November 2006	Coolant Level Sensor Replacement Information	All
<u>17 01 06</u>	SI	April 2011	Refilling Coolant Systems	All

<u>17 01 04</u>	SI	June 2004	Service Action: Transmission Oil Cooler Line Bracket	E65, E66
<u>18 02 99</u>	SI	November 2000	Exhaust System Back Pressure Check	All
<u>24 04 12</u>	SI	June 2012	ZF Automatic Transmission Oil Leaks, Diagnosis and Scope of Repairs	All
<u>24 05 11</u>	SI	December 2011	Transmission Failures Due to Incorrect Installation	All
<u>24 01 08</u>	SI	October 2010	ZF 6HP - Diagnosis for EGS FC 4F81	E60, E61, E65, E66, E70, E90, E91, E92, E93
<u>24 24 07</u>	SI	June 2012	TeileClearing (Enhanced Technical Support) for Automatic Transmissions	E53, E60, E61, E63, E64, E65, E66, E70, E71, E82, E83, E85, E86, E88, E89, E90, E91, E92, E93, F01, F02, F07, F10, F12, F13, F25, F30
<u>24 23 07</u>	SI	November 2009	6-Speed Automatic Transmissions Diagnosis and Troubleshooting Hints	E53, E60, E61, E63, E64, E65, E66, E70, E82, E83, E85, E86, E88, E90, E91, E92, E93
<u>24 18 07</u>	SI	November 2007	Programming a Replacement Transmission, Mechatronic, or VB-TEHCM	E38, E46, E53, E60, E61, E63, E64, E65, E66, E70, E82, E83, E85, E86, E88, E90, E91, E92, E93
<u>24 17 07</u>	SI	December 2007	Harsh 3-2 and/or 2-1 Downshifts	E65, E66
<u>24 14 07</u>	SI	June 2007	Noise from Driveshaft Area	E65, E66
<u>24 13 07</u>	SI	June 2007	Various Complaints Due to Poor Connection at Transmission Connector	E60, E61, E63, E64, E65, E66, E70, E90, E91, E92, E93
<u>24 10 06</u>	SI	November 2006	6HP26 EGS FC 507B After Transmission Replacement	E65, E66
<u>24 08 06</u>	SI	August 2011	ZF 6HP Transmissions - Mechatronic Sealing Sleeve Seepage	E53, E60, E61, E63, E64, E65, E66, E70, E85, E86, E90, E92, E93
<u>24 06 05</u>	SI	November 2005	Safety Recall Campaign 05V-504: Parking Lock Guide Plate	E53, E60, E63, E64, E65, E66
<u>24 06 03</u>	SI	August 2007	6HP26 Transmission Fault 4F53	E65, E66
<u>24 05 03</u>	SI	May 2003	Transmission Warning in Instrument Cluster	E65, E66
<u>24 09 00</u>	SI	April 2010	Automatic Transmission Repair & Replacement Information	All
<u>24 03 90</u>	SI	September 1990	Correct Adjustment of Shift Cable and Accelerator Cable	All
<u>26 01 06</u>	SI	June 2007	Noise from Driveshaft Area	E65, E66
<u>26 01 02</u>	SI	November 2002	Whine Noise From the Differential	All
<u>31 02 04</u>	SI	December 2004	Rattling Noise From Front or Rear Axle	All
<u>32 05 11</u>	SI	May 2011	Steering Wheel Leather Cover Is Peeling	All
<u>32 17 08</u>	SI	February 2010	Rubbing and/or Scraping Noise from the Steering Column	E46, E53, E60, E61, E63, E64, E65, E66, E70, E71, E82, E83, E85, E86, E88, E90, E91, E92, E93
<u>32 10 08</u>	SI	August 2008	Wheel Alignment Data	All
<u>32 02 05</u>	SI	June 2005	Chassis Integrated Module (CIM) Fault Code D98F "Timeout DME Message"	E65, E66
<u>32 01 03</u>	SI	March 2003	Steptronic Retrofit Installation	E65, E66
<u>32 02 01</u>	SI	July 2001	Replacement of Steering Gear Due to Accident Damage	All
<u>32 04 93</u>	SI	Sept 1993	Handling of Steering Box and Rack Core and Warranty Returns	All
<u>33 04 08</u>	SI	August 2009	Clicking or Cracking Noise from Rear Differential	E60, E61, E63, E64, E65, E66, E82, E85,

				E88, E90, E91, E92, E93
<u>33 03 08</u>	SI	April 2008	Differential Cover Sealer	All
<u>33 02 06</u>	SI	September 2006	Recall Campaign 06V-277: Inspect Rear Shock Absorbers	E60, E61, E63, E64, E65, E66
<u>34 04 10</u>	SI	April 2011	Recall Campaign 10V-446: Inspect Brake Booster Vacuum Supply Line	E60, E63, E64, E65, E66
<u>34 04 09</u>	SI	October 2009	Repair Procedures - Brake Disc/Rotor Removal	All
<u>34 03 09</u>	SI	August 2010	Brake Squeal from Pad Wear Sensor	E60, E61, E63, E64, E65, E66, E70, E71, E82, E88, E90, E91, E92, E93
<u>34 05 08</u>	SI	August 2008	Brake Rotor Minimum Thickness	E39, E46, E52, E53, E60, E61, E63, E64, E65, E66, E70, E71, E82, E83, E85, E86, E88, E90, E91, E92, E93
<u>34 03 08</u>	SI	May 2008	Parking Brake Repair Instructions	E65, E66
<u>34 05 05</u>	SI	June 2005	CBS Reset Not Possible After Brake Pad Replacement	E65, E66
<u>34 04 02</u>	SI	October 2002	Service Action to Reset Condition Based Service Data on Brake Pad Wear	E65, E66
<u>34 03 02</u>	SI	August 2002	Service Action to Modify Mounting Bracket of Right Rear Brake Pad Wear Sensor	E65, E66
<u>34 09 01</u>	SI	November 2001	New DOT 4 ESL Brake Fluid	All
<u>35 01 12</u>	SI	April 2012	Repairs to Clutch Pedal Assembly	All
<u>35 01 02</u>	SI	September 2002	Acceleration Pedal Feels "Notchy" at Times	E38, E39, E46, E52, E53, E65, E66
<u>36 01 10</u>	SI	November 2010	New Style Tire Valves	All
<u>36 01 08</u>	SI	August 2008	Tire Pressure Warning Caused by Damaged Wheel Electronics	E46, E60, E61, E63, E64, E65, E66, E70, E71, E82, E83, E85, E86, E88, E90, E91, E92, E93
<u>36 05 07</u>	SI	December 2007	Tire Warning Light Illuminated Due to Low Ambient Temperature	E60, E61, E63, E64, E65, E66, E70, E83, E85, E86, E90, E91, E92, E93
<u>36 03 07</u>	SI	September 2007	Flat Tire Monitor System (FTM) Diagnosis	E53, E60, E61, E63, E64, E65, E66, E83, E85, E90, E91
<u>36 04 06</u>	SI	April 2006	Nitrogen Inflated Tires	All
<u>36 05 05</u>	SI	June 2005	Tire Pressure Monitoring System (TPMS)	E39, E46, E52, E53, E60, E61, E63, E64, E65, E66, E83, E85, E90, E91
<u>36 03 04</u>	SI	April 2004	Tire Information Vehicle Placard	All
<u>36 01 04</u>	SI	November 2008	Hunter GSP97BMW Wheel Balancer-Features & Operator Training	All
<u>36 04 02</u>	SI	February 2003	Optional Run-Flat Tires on Model Year 2003 7 Series	E65, E66
<u>36 03 02</u>	SI	December 2002	Tire Pressure Monitoring System Won't Initialize	E65, E66
<u>36 01 99</u>	SI	April 1999	1999 Model Year Tire Applications	All
<u>36 03 97</u>	SI	February 1998	Tire Applications 1998 Model Year	All
<u>41 01 05</u>	SI	May 2005	Structural Aluminum Repair Precautions	All
<u>41 01 02</u>	SI	March 2002	Service Action to Check Trunk Lid for Cracks	E65
<u>41 02 00</u>	SI	December 2000	Wind Buffeting in Vehicle Interior	E12, E21, E23, E24, E28, E30, E31, E32, E34, E36, E38, E39, E46, E52, E53, E60, E63, E64, E65, E66, E83, R50, R53

<u>51 29 09</u>	SI	February 2012	1-Hour Windshield Urethane	All
<u>51 35 08</u>	SI	January 2009	Cracked or Damaged Windshields	E39, E46, E53, E60, E61, E63, E64, E65, E66, E70, E82, E83, E85, E86, E88, E90, E91, E92, E93
<u>51 01 08</u>	SI	February 2008	Door Does Not Latch Properly	E65, E66
<u>51 26 07</u>	SI	January 2009	Unpleasant Odor from the Trunk Area	E46, E65, E66
<u>51 30 06</u>	SI	January 2007	Rear Door Panel Cover Peeling	E65, E66
<u>51 21 06</u>	SI	September 2006	Glass Repair from BMW	All
<u>51 08 06</u>	SI	January 2006	Creaking Noise from Windshield or Dash Area	E65, E66
<u>51 23 05</u>	SI	July 2005	Front License Plate Bracket Mounting	E65, E66
<u>51 53 02</u>	SI	September 2006	Discoloration of Shadowline Trim	E46, E53, E60, E61, E63, E65, E66, E83
<u>51 07 02</u>	SI	December 2002	Roller Sunblind does Not Operate at Very Cold Temperatures	E65, E66
<u>51 05 02</u>	SI	April 2002	Leather Care	All
<u>52 03 06</u>	SI	February 2006	Retrofit of Manual Head Restraint Adjustment-Standard Seats	E65
<u>52 02 04</u>	SI	April 2005	Recall Campaign 04V-575: Modification of the Front Seat Heater Circuit	E60, E65, E66
<u>52 06 02</u>	SI	October 2002	Rear Seat Head Restraints Move on their Own	E65, E66
<u>52 05 02</u>	SI	October 2002	Reprogramming Rear Seat Head Restraints	E65, E66
<u>52 04 02</u>	SI	August 2002	Deformation of Upholstery on Front Seat Backrest Side Bolsters	E65, E66
<u>54 01 11</u>	SI	October 2011	Test Plans for Panoramic Roof	All
<u>54 08 05</u>	SI	July 2005	Retrofit of Sunroof One-Touch Closing Feature	E65, E66
<u>61 15 12</u>	SI	April 2012	Updated Battery Registration Procedure	All
<u>61 06 12</u>	SI	February 2012	The Airbag Warning Lamp Is Illuminated and SZL Fault Codes Are Stored	E60, E61, E63, E64, E65, E66
<u>61 17 09</u>	SI	November 2009	Diagnosis Gateway Module (OGW)	E65, E66
<u>61 11 09</u>	SI	June 2009	Battery Charging and Testing Procedure	All
<u>61 01 09</u>	SI	June 2012	Windshield Washer Malfunction	All
<u>61 18 08</u>	SI	January 2012	Battery Maintenance Requirements	All
<u>61 09 07</u>	SI	August 2007	OBD Socket Housing Cover Missing	E60, E65, E66, E83, E91, E92, E93
<u>61 01 07</u>	SI	April 2007	Wiring Harness Repairs	All
<u>61 16 06</u>	SI	October 2006	Battery Discharged by Lamp Module	E65, E66
<u>61 05 06</u>	SI	September 2007	Various Customer Complaints Corrected with Progman	E65, E66
<u>61 04 06</u>	SI	February 2006	Exiting a Vehicle that is Double-Locked from the Outside	All
<u>61 13 05</u>	SI	April 2011	Dead Battery - Energy Diagnosis Must Be Performed	E60, E61, E63, E64, E65, E66, E70, E71, E72, E82, E88, E89, E90, E91, E92, E93, F01, F02, F04, F07, F10, F25
<u>61 03 04</u>	SI	August 2004	Service Action: Program Control Units	E65, E66
<u>61 13 03</u>	SI	October 2003	Service Action to Replace Battery	E65, E66
<u>61 06 03</u>	SI	February 2010	BMW Maintenance Program - Replacement Wiper Inserts	All
<u>61 03 03</u>	SI	January 2006	CAN/Byteflight Bus Diagnostics	E60, E63, E64, E65, E66, E90, E91
<u>61 01 03</u>	SI	March 2003	Service Action to Replace Central Gateway Module (ZGM)-Phase 2	E65, E66
<u>61 16 02</u>	SI	December 2002	Battery Warranty Claims	All
<u>61 15 02</u>	SI	November 2011	MOST Bus Diagnosis	All
<u>61 11 02</u>	SI	October 2002	Poor Windshield Washer Spray Pattern	E65, E66
<u>61 10 02</u>	SI	October 2002	Window Initialization Procedure	E65, E66

<u>61 09 02</u>	SI	October 2002	Service Action to Replace Central Gateway Module (ZGM)	E65, E66
<u>61 05 02</u>	SI	June 2002	Recall Campaign 02V-150: Reprogram Fuel Pump	E65, E66
<u>61 03 02</u>	SI	June 2002	Service Action to Replace Trunk Switch	E65
<u>61 02 02</u>	SI	March 2002	Keys and Vehicle Security	All
<u>61 08 00</u>	SI	May 2012	Closed-Circuit Current Measurement	All
<u>61 07 00</u>	SI	July 2000	Windshield Wiper Blades are Noisy, or Do Not Clean Properly	All
<u>61 05 00</u>	SI	November 2004	Stabilant 22A Electrical Contact Enhancer	All
<u>61 02 00</u>	SI	April 2000	Wiring Repair Proc. for Firing Circuits of Airbag Systems	All
<u>61 05 93</u>	SI	November 1993	Jump Starting of Vehicles	All
<u>62 06 12</u>	SI	April 2012	Maximum Permissible Speedometer Deviations	All
<u>62 03 09</u>	SI	August 2010	Outside Temperature Display Is Incorrect	E39, E46, E53, E60, E61, E65, E66, E70, E71, E82, E83, E85, E86, E88, E90, E91, E92, E93, F02
<u>62 09 06</u>	SI	October 2006	Outside Temperature Display Incorrect	E38, E39, E46, E52, E53, E65, E66
<u>62 04 02</u>	SI	October 2002	Clock Loses Time	E65, E66
<u>62 03 02</u>	SI	October 2002	Service Action to Replace Instrument Cluster	E65
<u>62 02 02</u>	SI	January 2003	Instrument Cluster and Control Display Revert to Metric Units	E65, E66
<u>63 02 10</u>	SI	July 2010	Check Control Message Displayed; Turn Signals Flash Fast	E65, E66
<u>63 07 09</u>	SI	March 2010	Lights Do Not Switch Off Automatically	E60, E61, E63, E64, E65, E66
<u>63 04 08</u>	SI	November 2009	Headlamp Moisture: Fault Diagnostics	All
<u>63 13 06</u>	SI	December 2010	Automatic Headlamp System Does Not Switch Off The Lights	E46, E53, E60, E61, E63, E64, E65, E66, E83, E85, E90, E91, E92
<u>63 05 06</u>	SI	October 2006	Automatic Headlamps: Lights Do Not Switch Off	E60, E63, E64, E65, E66
<u>63 05 02</u>	SI	October 2002	Automatic Low Beam Switched on in Bright Conditions	E39, E46, E53, E65, E66
<u>63 01 02</u>	SI	February 2002	Service Action to Recode E65 Light Module	E65
<u>63 02 01</u>	SI	August 2010	Light Bulb Replacement - Incandescent and Halogen Light Bulbs	All
<u>63 01 01</u>	SI	February 2001	Xenon Lamp Color after Bulb Replacement	All
<u>63 02 88</u>	SI	October 1988	Center High Mounted Stop Lamp	All
<u>63 02 87</u>	SI	June 1987	Cleaning of Plastic Parts	All
<u>64 09 10</u>	SI	September 2010	Refrigerant and Compressor Oil Reuse	All
<u>64 05 08</u>	SI	October 2008	Damage to the Air Conditioning Control Panel	All
<u>64 02 08</u>	SI	April 2009	Whistling from the Heating/Air Conditioning Unit at Speeds over 50 MPH	All
<u>64 20 06</u>	SI	November 2006	Poor Performance From Heating and Air Conditioning System	E65, E66
<u>64 22 05</u>	SI	December 2005	Blower Motor Operates at Reduced Speed	E65, E66
<u>64 21 05</u>	SI	May 2010	Troubleshooting Air Conditioning Compressor Noise	All
<u>64 04 03</u>	SI	October 2004	Air Conditioning System Musty Odor	All
<u>64 02 03</u>	SI	June 2003	Air Conditioning Refrigerant Fill Capacities and Information	All
<u>64 04 02</u>	SI	February 2006	Replacement A/C Compressor Information Insert	All
<u>64 13 92</u>	SI	October 1992	Nominal A/C System Pressures R-12/R-134a	All

<u>64 10 92</u>	SI	April 1992	R134a A/C Troubleshooting	All
<u>64 08 91</u>	SI	October 2006	Musty Odors from Air Conditioning System	E39, E46, E53, E60, E61, E63, E64, E65, E66, E85
<u>64 06 91</u>	SI	September 1991	A/C Compressor - WPAC	All
<u>65 09 11</u>	SI	November 2011	Entertainment and Communication Systems are Inoperative Intermittently	E60, E61, E63, E64, E65, E66, E70, E71, E72, E82, E83, E85, E86, E88, E89, E90, E91, E92, E93
<u>65 02 10</u>	SI	February 2010	Aftersales Retrofit Installation Problems	All
<u>65 19 09</u>	SI	June 2009	ISTA/P Prompts to Replace CDC	E65, E66
<u>65 15 09</u>	SI	May 2009	DWA Siren Too Quiet When Locking and Unlocking	E46, E60, E61, E65, E66, E70, E71, E82, E88, E90, E91, E92
<u>65 07 09</u>	SI	April 2011	Navigation System Has Missing or Incorrect Road Map Data	E38, E39, E46, E52, E53, E60, E61, E63, E64, E65, E66, E70, E71, E72, E82, E83, E85, E86, E88, E89, E90, E91, E92, E93, F01, F02, F04, F07, F10, F25
<u>65 13 08</u>	SI	January 2009	Radio Has Constant Static Noise	E65, E66
<u>65 05 08</u>	SI	April 2008	SIRIUS Radio Station List Is Not Displayed in the RSE Monitor	E65, E66
<u>65 04 08</u>	SI	April 2008	"Call SIRIUS" Is Displayed	E39, E46, E53, E60, E61, E63, E64, E65, E66, E70, E71, E82, E83, E85, E86, E88, E90, E91, E92, E93
<u>65 42 07</u>	SI	January 2008	Alarm Triggers Unexpectedly - Troubleshooting	All
<u>65 16 07</u>	SI	July 2007	MOST Bus Component(s) Inoperative	E65, E66
<u>65 07 07</u>	SI	July 2011	SDARS SIRIUS Radio is Intermittently Inoperative	E39, E46, E53, E60, E61, E63, E64, E65, E66, E70, E71, E72, E82, E83, E85, E86, E88, E89, E90, E91, E92, E93, F01, F02, F04, F07, F10, F10H, F12, F13, F25
<u>65 75 06</u>	SI	March 2012	Airbag Warning Lamp for OC3 Seat Mat Fault	E53, E60, E61, E63, E64, E65, E66, E83, E85, E90, E91
<u>65 71 06</u>	SI	February 2006	Airbag Warning Lamp Lit; FC 9763/97FD in SSFA/SSBF	E65, E66
<u>65 64 06</u>	SI	October 2006	Tips on Installing and Enabling OC3 Seat Occupancy Mat	E60, E65, E66, E83, E85
<u>65 52 06</u>	SI	October 2006	Airbag Fault 97C9: Passenger Seat Satellite	E65, E66
<u>65 51 06</u>	SI	December 2006	DIS Test Plan Error While Performing SIM/SGM Self Test	E60, E61, E63, E64, E65, E66
<u>65 32 06</u>	SI	December 2006	Volume Adjustment after MOST-Bus Interruption	E65, E66
<u>65 10 06</u>	SI	May 2006	New Audio-Test-CD for Diagnosing a Faulty CD/Audio-DVD Drive or Media	All
<u>65 04 06</u>	SI	March 2006	KL-R Stays On After Ignition Off - Comfort Access Only	E60, E61, E63, E64, E65, E66, E90, E91
<u>65 49 05</u>	SI	March 2005	DVD Navigation System is Inoperative at Low Ambient Temperatures	E65, E66
<u>65 48 05</u>	SI	January 2007	Navigation System Has Missing Or Incorrect DVD/CD Road Map Data	E38, E39, E46, E53, E60, E61, E63, E64, E65, E66, E70, E83, E85, E86, E90, E91, E92



<u>65 41 05</u>	SI	February 2005	Rear Side/Thorax Airbags, Resistance Too High	E65, E66
<u>65 40 05</u>	SI	August 2006	Passenger Airbag Status Lamp Goes ON/OFF During Driving	E60, E65, E66, E83, E85, E90
<u>65 38 05</u>	SI	October 2006	AWL Illuminated, with Wiring Faults for Active Head Restraint	E60, E65, E66
<u>65 35 05</u>	SI	January 2006	STVL/STVR Pressure Sensor Faults	E65, E66
<u>65 33 05</u>	SI	January 2006	Service Action: Reprogram Control Units for Airbag Warning Lamp	E65, E66
<u>65 25 05</u>	SI	August 2009	HD Radio - Functionality and Diagnosis	E60, E61, E63, E64, E65, E66, E70, E71, E82, E83, E85, E86, E88, E89, E90, E91, E92, E93, F01, F02, F07
<u>65 18 05</u>	SI	January 2006	MP3 Compatibility Overview	E46, E53, E60, E61, E63, E64, E65, E66, E83, E85, E90, E91
<u>65 03 05</u>	SI	July 2007	Low Hands-free Audio Volume and/or Popping/Crackling Noise after TCU Programming	E65, E66
<u>65 02 05</u>	SI	February 2012	SIRIUS Satellite Radio: How It Works	E39, E46, E53, E60, E61, E63, E64, E65, E66, E70, E71, E72, E82, E83, E85, E86, E88, E89, E90, E91, E92, E93, F01, F02, F04, F07, F10, F10H, F12, F13, F25, F30
<u>65 19 04</u>	SI	February 2012	E65/E66 Conversion Procedure - CD NAV (NAV101) to DVD NAV (NAV102)	E65, E66
<u>65 13 04</u>	SI	June 2004	Various "Self-test" Faults Stored in "Byteflight" Modules	E60, E63, E64, E65, E66, E85
<u>65 12 04</u>	SI	September 2004	Recall Campaign 04V-379: Driver's Seat Occupant Detection	E65, E66
<u>65 11 04</u>	SI	November 2004	Service Action: Program Control Units for Airbag Warning Lamp	E65, E66
<u>65 07 04</u>	SI	November 2004	Procedures to Enter the Radio Service Mode	E39, E46, E52, E53, E65, E66, E83, E85
<u>65 01 04</u>	SI	July 2008	AM/FM Radio Reception Problems - Radio/Antenna Diagnosis	E12, E21, E23, E24, E28, E30, E31, E32, E34, E36, E38, E39, E46, E52, E53, E60, E61, E63, E64, E65, E66, E70, E71, E82, E83, E85, E86, E88, E90, E91
<u>65 27 03</u>	SI	August 2003	Navigation Computer is Inoperative at High Ambient Temperatures	E65, E66
<u>65 26 03</u>	SI	March 2003	NAV Voice Only Female	E52, E65, E66
<u>65 24 03</u>	SI	August 2010	Passenger Airbag Status Lamp	All
<u>65 11 03</u>	SI	June 2003	AVT (Antenna Tuner) is Inoperative at High Ambient Temperatures	E65, E66
<u>65 02 03</u>	SI	October 2003	Control Display Blank at High Ambient Temperatures	E65, E66
<u>65 21 02</u>	SI	October 2010	Navigation System Operating Software	E38, E39, E46, E53, E65, E66, E83, E85, E86
<u>65 20 02</u>	SI	December 2004	NAV Voice Message and/or Text is in German or French	E65, E66
<u>65 17 02</u>	SI	May 2002	Service Action to recode satellite sensor (SBSR)	E65, E66
<u>65 12 02</u>	SI	December 2002	Window Tint Affects Radio Reception and Remote Range	All
<u>65 01 02</u>	SI	March 2002	E65 Radio Station "Name" is displayed instead of Frequency	E65, E66

<u>65 09 93</u>	SI	Oct 1993	Care and Cleaning for Compact Discs	All
<u>65 21 92</u>	SI	June 1993	Model Year 1993 Radios	All
<u>66 10 10</u>	SI	October 2010	Diagnosis Tips - Integrated Universal Remote Control (UGDO)	All
<u>66 02 08</u>	SI	February 2008	Comfort Access is Inoperative	E65, E66
<u>66 07 06</u>	SI	December 2006	Remote Control Key Not Working	E38, E39, E46, E52, E53, E60, E65, E66, E85
<u>66 06 06</u>	SI	October 2006	Replacement Remote Key Inoperative	E65, E66
<u>66 04 06</u>	SI	March 2007	Night Vision Malfunctions and Parts Replacement	E60, E61, E63, E64, E65, E66
<u>66 03 06</u>	SI	May 2006	Comfort Access Function is Inoperative	E65, E66
<u>66 02 06</u>	SI	February 2006	Active Cruise Control II (ACC II) Adjustment Test Plan Error	E65, E66
<u>66 01 05</u>	SI	August 2005	Trunk Opening Function Via Remote Control is Inoperative	E65, E66
<u>66 01 03</u>	SI	September 2009	315 MHz Remote Control Range is Inadequate	E65, E66
<u>66 01 02</u>	SI	August 2003	Service Action to Replace the Antenna Amplifier and Remotes	E65, E66
<u>66 10 90</u>	SI	October 1990	Cruise Control Electrical Troubleshooting	All
<u>66 10 89</u>	SI	December 1989	Troubleshooting Remote Control Vehicle Security System	All
<u>72 31 06</u>	SI	October 2006	Rear Seat Occupancy Detection, Belt Buckle	E65, E66
<u>72 04 03</u>	SI	February 2006	Seat Belt Tensioner Faults, High Resistance	E65, E66
<u>72 06 96</u>	SI	Sept 1996	Transportation of Infants and Children in all BMWs - incl. Z3	All
<u>84 02 12</u>	SI	May 2012	CDMA Telematics Control Unit (TCU) Replacement Procedure	E46, E53, E60, E61, E63, E64, E65, E66, E70, E71, E83, E85, E86, E90, E91, E92, E93
<u>84 04 11</u>	SI	September 2011	BMW ASSIST Troubleshooting	All
<u>84 03 11</u>	SI	September 2011	Combox Replacement Part Activation via DCSnet for BMW Assist	All
<u>84 02 11</u>	SI	May 2011	Diagnosis of Communication Systems	All
<u>84 06 10</u>	SI	September 2010	Telephone: Ringtone Intermittently Too Loud	All
<u>84 04 10</u>	SI	October 2010	General Bluetooth Information	All
<u>84 12 09</u>	SI	November 2009	BMW Assist System Capabilities and Services by Model Year	E46, E53, E60, E61, E63, E64, E65, E66, E70, E71, E83, E85, E86, E89, E90, E91, E92, E93, F01, F02, F07
<u>84 01 09</u>	SI	April 2009	Service Action: Reactivation of Telematics Control Unit (TCU)	E46, E53, E60, E61, E63, E64, E65, E66, E70, E82, E83, E85, E86, E90, E91, E92, E93
<u>84 08 08</u>	SI	September 2008	BMW Assist Menu Item	All
<u>84 02 08</u>	SI	March 2008	Service Action: Initialize BMW Assist Services	E60, E61, E63, E64, E65, E66, E70, E82, E90, E91, E92
<u>84 01 08</u>	SI	June 2008	Pairing Between the iPhone and the Vehicle Fails	E60, E61, E63, E64, E65, E66, E70, E83, E85, E90, E92, E93
<u>84 21 07</u>	SI	November 2007	Diagnosis When an Unapproved Handset is Paired to a Vehicle	E46, E53, E60, E61, E63, E64, E65, E66, E70, E83, E85, E86, E90, E91, E92, E93
<u>84 20 07</u>	SI	October 2008	Upgrading BMW Assist to Support New Bluetooth Handsets	E46, E53, E60, E61, E63, E64, E65, E66,

<u>84 19 07</u>	SI	October 2007	One Way Audio when Using a Bluetooth Enabled Handset	E70, E83, E85, E86, E90, E91, E92, E93 E46, E53, E60, E61, E63, E64, E65, E66, E70, E83, E85, E86, E90, E91, E92, E93
<u>84 18 07</u>	SI	June 2009	Enable Services Status Bar Does NOT Progress	E60, E61, E63, E64, E65, E66, E70, E90, E91, E92, E93
<u>84 17 07</u>	SI	July 2008	SOS Inactive Warning Message, No Communication with TCU	E60, E61, E63, E64, E65, E66, E70, E90, E91, E92, E93
<u>84 05 07</u>	SI	August 2007	Checking NAD Signal Strength for BMW Assist	E60, E61, E63, E64, E65, E66, E70, E90, E91, E92, E93
<u>84 04 07</u>	SI	March 2007	Bluetooth Handsets No Longer Pairs to the Vehicle	E46, E53, E60, E61, E63, E64, E65, E66, E70, E83, E85, E86, E90, E91
<u>84 02 07</u>	SI	March 2007	Service Action: Activation of Telematics Control Unit (TCU)	E60, E61, E63, E64, E65, E90, E91
<u>84 57 06</u>	SI	November 2006	CPT9000 Handset Doesn't Turn On With The Ignition	E65, E66
<u>84 56 06</u>	SI	November 2006	Phone Board Displays Double Digit Entry On Display	E65, E66
<u>84 52 06</u>	SI	October 2006	CPT9000 Phone Hands-Free Audio in Vehicle is Too Low	E65, E66
<u>84 51 06</u>	SI	October 2006	The BMW Assist "Embedded" Phone Rings Erroneously in the Vehicle	E46, E53, E60, E63, E64, E65, E66, E83, E85
<u>84 49 06</u>	SI	October 2007	Vehicle Dials BMW Assist on its Own	E46, E53, E60, E61, E63, E64, E65, E66, E70, E83, E85, E86, E90, E91, E92, E93
<u>84 41 06</u>	SI	November 2006	CPT9000 Interference Noise in Hands-Free Mode	E65, E66
<u>84 34 06</u>	SI	November 2006	2005 MY E65 No Telephone Hands Free Audio	E65, E66
<u>84 30 06</u>	SI	November 2006	VV710 Bluetooth Handset Does Not Charge In Docking Cradle	E46, E53, E60, E63, E64, E65, E66, E83, E85
<u>84 18 06</u>	SI	June 2006	"Low Bluetooth Signal" Displayed in Handset or Bluetooth Connection is Lost	E46, E53, E60, E61, E63, E64, E65, E66, E83, E85, E90, E91
<u>84 17 06</u>	SI	March 2008	CPT9000 Handset Does Not Power On When The Ignition Is Cycled On	E65, E66
<u>84 16 06</u>	SI	August 2006	BMW Assist Inoperative After Transportation Mode is Cleared	E46, E53, E60, E61, E63, E64, E65, E66, E83, E85, E90
<u>84 14 06</u>	SI	May 2007	Service Action: Reactivation of Telematics Control Unit (TCU)	E46, E53, E60, E61, E63, E64, E65, E66, E83, E85, E90, E91
<u>84 12 06</u>	SI	April 2006	Cannot Initiate a Phone Call Using Voice Recognition-CDMA Handset in Ext Roaming	E65, E66
<u>84 11 06</u>	SI	February 2012	Swapping TCUs for Testing	E46, E53, E60, E61, E63, E64, E65, E66, E70, E71, E72, E82, E83, E85, E88, E89, E90, E91, E92, E93, F01, F02, F04, F07
<u>84 10 06</u>	SI	August 2007	BMW Assist or Bluetooth Inoperative, TCU FC# A373	E60, E61, E63, E64, E65, E66, E90, E91, E92, E93
<u>84 05 06</u>	SI	March 2007	Diagnosis of Bluetooth Handset Related Complaints	E46, E53, E60, E61, E63, E64, E65, E66, E70, E83, E85, E86, E90, E91, E92, E93

<u>84 04 06</u>	SI	March 2006	Service Action: Reactivation of Telematics Control Unit (TCU)	E46, E53, E60, E64, E65, E66, E83, E85
<u>84 02 06</u>	SI	January 2006	Hands free Bluetooth Phone Call may be Lost if a Call Waiting Call is Received	E46, E53, E60, E61, E63, E64, E65, E66, E83, E85, E90, E91
<u>84 22 05</u>	SI	April 2010	Reactivation of BMW Assist Services	E46, E53, E60, E61, E63, E64, E65, E66, E70, E71, E83, E85, E86, E89, E90, E91, E92, E93, F01, F02, F07
<u>84 21 05</u>	SI	September 2005	BMW Assist is not Selectable After Programming with CIP 19.1	E65, E66
<u>84 20 05</u>	SI	September 2005	"READING DATA" is Displayed in the Control Display	E65, E66
<u>84 17 05</u>	SI	August 2006	Service Action: Check Telematics Control Unit (TCU) and Replace if Necessary	E65, E66
<u>84 16 05</u>	SI	August 2005	SiemensS66 Handset Will Not Pair To The Vehicle	E65, E66
<u>84 13 05</u>	SI	May 2007	Bluetooth Phone Call May Still be Displayed as Active after the Call has Ended	E46, E53, E60, E61, E63, E64, E65, E66, E70, E83, E85, E90, E91, E92, E93
<u>84 06 05</u>	SI	June 2005	TCU Fails to Code CoApi 1000 General Fault	E65, E66
<u>84 13 04</u>	SI	November 2007	BMW Assist with Integrated Bluetooth	E46, E53, E60, E61, E63, E64, E65, E66, E70, E83, E85, E86, E90, E91, E93
<u>84 06 04</u>	SI	May 2005	CPT9000 Handset Not Recognized	E65, E66
<u>84 16 03</u>	SI	September 2003	BMW Universal Bluetooth Hands-Free System Pairing Difficulties	All
<u>84 15 03</u>	SI	April 2010	Initialization of BMW Assist Services	E60, E61, E63, E64, E65, E66, E70, E71, E72, E82, E88, E89, E90, E91, E92, E93, F01, F02, F04, F07
<u>84 14 03</u>	SI	August 2003	CPT9000 Telephone Retrofit Wiring Instructions Error	E65, E66
<u>84 13 03</u>	SI	June 2005	Reactivation of CPT9000 TCU	E65, E66
<u>84 04 03</u>	SI	February 2003	CPT8000 Does Not Function Correctly When Connected to Vehicle	E38, E39, E46, E52, E53, E65, E66
<u>84 01 03</u>	SI	December 2005	CPT9000 Telephone	E46, E53, E60, E65, E66, E83, E85
<u>84 06 02</u>	SI	March 2002	E65 Notepad Feature of SVS only Plays 3 Seconds of ea. Note	E65
<u>84 05 02</u>	SI	August 2002	Phoneboard is Inoperative	E65, E66
<u>99 01 08</u>	SI	September 2008	Environmental Paint Damage Repair	All
<u>99 01 06</u>	SI	October 2006	Spots in Paint Under Foam Tape	E53, E60, E63, E64, E65, E66, E70, E83, E85, E86, E90, E91, E92
<u>99 02 02</u>	SI	February 2003	Polishing Out Paint Surface Imperfections	All
<u>99 01 01</u>	SI	June 2001	Paint Work Manual	All