



## Official

# Carly Diagnostics Report

**5 (E60), Build Year 2008**

categorized as Upper middle class was diagnosed with Carly on

**Aug 12 2019**

---

**Carly found 27 control units.**

**7 fault codes were detected.**

---



### Motor Control

<b>Engine / Motor</b>	
ECU OK, no Fault Code	





## ABS / DSC / Brake

### Dynamische Stabilitaets Kontrolle / DSC

**Fault Code:** 006E83

**Fault Explanation:** :PT-CAN: Signal ST IND FLTR message in STAT RDC (ID 0x31C) invalid (transmitter RDC) Please feel free to FC hide (Bosch software error) / PT-CAN: Signal ST IND FLTR message in STAT RDC; ID invalid 0x31C; RDC transmitter --- (DSC: Tire Pressure Control: interface)



## Airbag

### Advanced Crash and Safety Management (ACSM)

ECU OK, no Fault Code



## Transmission Control

### Gear switch / Gangschalter

ECU OK, no Fault Code





## Instrumentation

<b>Instrument cluster / Kombiinstrument</b> ECU OK, no Fault Code	✓
<b>Central info display / Zentrales Display</b> ECU OK, no Fault Code	✓



## Light/Rain Control

<b>Rain/light sensor / Regen-Lichtsensoren RLS</b> ECU OK, no Fault Code	✓
<b>Light / Licht</b> <b>Fault Code:</b> 009CBF <b>Fault Explanation:</b> :Caution: electronics at the right headlight (SMC) reports errors / Battery deep discharge <b>Fault Code:</b> 009CC5 <b>Fault Explanation:</b> :RLS: NoResponse	✗



## Heating / AC

<b>Air conditioning / Klimaanlage</b> ECU OK, no Fault Code	✓
--	---



## Immobilizer System

<b>CAS</b> ECU OK, no Fault Code	✓
-------------------------------------	---



## Sunroof / Roof

<b>Sunroof / Schiebedach</b> ECU OK, no Fault Code	✓
---	---



## Audio / Navigation / Communication

<b>Phone / Telefon</b> ECU OK, no Fault Code	✓
<b>Digital Satellite-Tuner USA</b> <b>Fault Code:</b> 00A536 <b>Fault Explanation:</b> :Error SatAntenna Open Circuit. <b>Fault Code:</b> 00A530 <b>Fault Explanation:</b> :Error Power Supply Fault.	✗
<b>Car Communication Computer CCC</b> ECU OK, no Fault Code	✓

<b>MASK</b>	✓
ECU OK, no Fault Code	
<b>Center-Konsole</b>	✓
ECU OK, no Fault Code	



## Seats

<b>Seats / Sitze</b>	✓
ECU OK, no Fault Code	
<b>Seats / Sitze</b>	✓
ECU OK, no Fault Code	



## Systems

<b>Gateway</b>	✓
ECU OK, no Fault Code	
<b>Steering column switch / Lenkstockschalter</b>	✓
ECU OK, no Fault Code	
<b>Tire pressure control / Reifendruck Kontrolle</b>	✓
ECU OK, no Fault Code	
<b>Passive Go System</b>	✓
ECU OK, no Fault Code	



## Anti-theft alarm system

<b>Interior protection / Innenraumschutz</b> ECU OK, no Fault Code	✓
<b>Theft alarm / Diebstahl Warnanlage</b> ECU OK, no Fault Code	✓



## Chassis

<b>Central Control / Zentrale Bedieneinheit</b> ECU OK, no Fault Code	✓
--	---



## Body

<b>Car Body Module</b> ECU OK, no Fault Code	✓
---	---



## Other

### ULF2\_HI

**Fault Code:** 00DE50

**Fault Explanation:** :Ring break diagnosis was performed (Error ring diagnosis)

**Fault Code:** 00A9AC

**Fault Explanation:** :Overvoltage on the control unit measured (Error Battery Voltage Fault).

X